

Troubleshooting-data

Model: Wagon R+ 1,2 4WD Motor: K12A / Suzuki SMPI

Component:	From:	To:	Condition:	Value	Measure Ri x.
			Connector seen from wire side		
Battery (earth)	A13	Batt	Ignition on	0 V	
Battery (earth)	A3	Batt	Ignition on	0 V	
Battery (earth)	C21	Batt	Ignition on	0 V	
Air temperature sensor	A26	Batt	Ignition on	0 V	
Air temperature sensor	C19	Batt	Ignition on, 20°C air temperature	2,0 - 2,7 V	
Battery (possitive)	C13	Batt	Ignition on	10 - 14 V	
Battery (possitive)	C13	Batt	Ignition off	10 - 14 V	
Canister purge valve	A12	Batt	Ignition on	10 - 14 V	
Canister purge valve	A12	Batt	Idle, rev up briefly		1028
Coolant temperature sensor	A26	Batt	Ignition on	0 V	
Coolant temperature sensor	C9	Batt	Ignition on, 80°C	0,5 - 0,95 V	
Coolant temperature sensor	C9	Batt	Ignition on, 0°C	3.3 - 3,8 V	
Coolant temperature sensor	C9	Batt	Ignition on, 50°C	1,4 - 1,7 V	
EGR valve	A4	Batt	Ignition on	10 - 14 V	
EGR valve	A4	Batt	Idle, warm		1028
Idle step motor	B10	Batt	Idle		1033
Idle step motor	B11	Batt	Idle		1033
Idle step motor	B12	Batt	Idle		1028
Idle step motor	B2	Batt	Idle		1033
Ignition	C10	Batt	Ignition on	10 - 14 V	
Ignition	C10	Batt	Ignition off	0 V	
Ignition amplifier	A24	Batt	Idle	0 ~ 5 V	1049
Inductive sensor	C2	C3	Starter rpm		1045
Injector cyl. 1	A1	Batt	Ignition on	10 - 14 V	
Injector cyl. 1	A1	Batt	Idle, warm	2 - 4 ms	1004
Injector cyl. 2	A14	Batt	Ignition on	10 - 14 V	
Injector cyl. 2	A14	Batt	Idle, warm	2 - 4 ms	1004
Injector cyl. 3	A2	Batt	Ignition on	10 - 14 V	
Injector cyl. 3	A2	Batt	Idle, warm	2 - 4 ms	1004
Injector cyl. 4	A15	Batt	Ignition on	10 - 14 V	
Injector cyl. 4	A15	Batt	Idle, warm	2 - 4 ms	1004
Knock sensor	C7	Batt	Ignition on	2,1 - 2,9 V	1040
Knock sensor	C7	Batt	Idle, rev up briefly		1040
MAP sensor	C15	Batt	Ignition on	4,75 - 5,25 V	
MAP sensor	C4	Batt	Ignition on	3,3 - 4 V	
MAP sensor	A26	Batt	Ignition on	0 V	
MAP sensor	C4	Batt	Idle	0,4 - 2 V	
O2-sensor with pre-heater	A16	Batt	Ignition on	10 - 14 V	

Troubleshooting-data

Model: Wagon R+ 1,2 4WD Motor: K12A / Suzuki SMPI

Component:	From:	To:	Condition:	Value	Measure di c.
O2-sensor with pre-heater	C5	A26	ldle, warm	0,1 ~ 1 V	1018
Pump relay	A10	Batt	Ignition on	10 - 14 V	
Pump relay	A10	Batt	Starter rpm	0 - 1 V	
System relay	C12	Batt	Ignition on	0 - 2 V	
System relay	C11	Batt	Ignition on	10 - 14 V	
System relay	C12	Batt	Ignition off	10 - 14 V	
System relay	C11	Batt	Ignition off	0 V	
Throttle valve potentiometer	A26	Batt	Ignition on	0 V	
Throttle valve potentiometer	C15	Batt	Ignition on	4,75 - 5,25 V	
Throttle valve potentiometer	C6	Batt	Ignition on, throttle valve closed	0,2 - 1 V	
Throttle valve potentiometer	C6	Batt	Ignition on, throttle valve fully open	2,8 - 4,8 V	